

www.competitiondata.com

Track Master and Command Link Software Troubleshooting Guide

Updated – March 2004

Operating System Compatibility Statement

CDS Software is designed to operate on the Windows operating system, version 98 SE and higher.

For maximum compatibility with operating systems **other than** Win 98 SE we recommend F35 or higher ROM and TM and CL 5.4 or higher.

CDS does not guarantee compatibility with any operating system.

COMPETITION DATA SYSTEMS, INC 8050 WEHRLE DRIVE WILLIAMSVILLE, NY, USA 14221 Voice: (716) 631-2880 Fax: (716) 631-9930

On the web at www.competitiondata.com

PROBLEM

CAUSE and/or SOLUTION

ISSUE # CL-1

Command Link or Command View *View Live Readings*" fails. Problem occurs intermittently.

Applies to:

- Windows 95, 98 on certain PCs particularly Dell Notebook computers
- Windows 2000 Professional (may apply to NT 4.0)
- ALL Commander II ROM versions
- Command Link versions 5.2 and lower

Adjust COM port settings in windows as follows:

- Right Click on "My Computer"
- Select Properties
- (Click Hardware in Win 2000)
- Click Device Manager
- Double click on **Ports**
- Double Click on the COM Port you are using with Commander
- Click Properties
- Click Port Settings
- Click Advanced
- Try each of the following setting combinations, starting with the first one shown. You MUST re-boot your PC after each setting change for it to take affect.
 - After each change, press the reset button on the Commander II and then try to View Live Readings.

		×
✓ Use <u>FIFO</u> buffers (requires 16550 compatible UART) ·		ОК
Select lower settings to correct connection problems.		Cancel
Select higher settings for faster performance.		
Receive Buffer: Low (1)	High (14)	<u>D</u> efaults
Iransmit Buffer: Low (1)	High (16)	
· · · · · · · · · · · · · · · · · · ·		
vanced Port Settings		×
Use EIFO buffers (requires 16550 compatible UART)		OK
Select lower settings to correct connection problems. Select higher settings for faster performance.		Cancel
Receive Buffer: Low (1)	High (14)	<u>D</u> efaults
	109011-41	
Iransmit Buffer: Low (1)	High (16)	
vanceu Port Settings		×
		ОК
Use EIFO buffers (requires 16550 compatible UART) Select lower settings to correct connection problems.		
Use EIFO buffers (requires 16550 compatible UART) Select lower settings to correct connection problems. Select higher settings for faster performance.		OK
Use EIFO buffers (requires 16550 compatible UART) Select lower settings to correct connection problems. Select higher settings for faster performance.	High (14)	OK Cancel
Use EIFO buffers (requires 16550 compatible UART) Select lower settings to correct connection problems. Select higher settings for faster performance. Beceive Buffer: Low (1)	High (14) High (16)	OK Cancel
Use EIFO buffers (requires 16550 compatible UART) Select lower settings to correct connection problems. Select higher settings for faster performance. Beceive Buffer: Low (1)		OK Cancel
Select higher settings for faster performance. Eleceive Buffer: Low (1) Irensmit Buffer: Low (1)		OK Cancel Defaults
Use EIFO buffers (requires 16550 compatible UART) Select lower settings to correct connection problems. Select higher settings for faster performance. Beceive Buffer: Low (1)		OK Cancel
Use EIFO buffers (requires 16550 compatible UART) Select lower settings to correct connection problems. Select higher settings for faster performance. Beceive Buffer: Low (1)		OK Cancel Defaults
Use EIFO buffers (requires 16550 compatible UART) Select lower settings to correct connection problems. Select higher settings for faster performance. Eleceive Buffer: Low (1) IrensmitBuffer: Low (OK Cancel Defaults
Use EIF0 buffers (requires 16550 compatible UART) Select lower settings to correct connection problems. Select higher settings for faster performance. Beceive Buffer: Low (1) Irensmit Buffer: Low (1) Vanced Port Settings ✓ Use EIF0 buffers (requires 16550 compatible UART) Select lower settings to correct connection problems. Select lower settings to correct connection problems. Select lower settings to faster performance.	High (16)	OK Cancel Defaults X
Use EIFO buffers (requires 16550 compatible UART) Select lower settings to correct connection problems. Select higher settings for faster performance. Eleceive Buffer: Low (1) IrensmitBuffer: Low (OK Cancel Defaults X

PROBLEM	CAUSE and/or SOLUTION			
PROBLEM ISSUE # CL-1 (Continued)	 CAUSE and/or SOLUTION Click ok to get out IMPORTANT: you MUST Re-Boot your PC for changes to take effect. NOTE: You may have to try to "view live' repeatedly, some of the time you will get "Unable to send command" message. If you get an error message in CL, press the Reset button on the front of the Commander II just before you click the View Live button in CL again. NOTE: If you still can not view live, try pressing the Reset button on the front of the Commander II just before you click the View Live button in CL. Make sure green light on front of Commander II is flashing slowly 			
	before you attempt a communication command (such as <i>View Live Readings</i> etc.). If it is not, press the Reset button on the front of the Commander II.			
 ISSUE # CL-2 Command Link Upload Configuration fails Applies to: Commander II ROM versions ALL Command Link versions 5.2 and lower. 	 SOLUTION #1 Perform the steps listed in issue #CL-1 (above) If all of the above fail to solve your problem, try pressing the reset button on the Commander II right before you send it a command NOTE: Make sure green light on front of Commander II is flashing slowly before you attempt a communication command (such as <i>View Live Readings</i> etc.) If it is not, press the Reset button on the front of the Commander II. SOLUTION #2 If you already are running TM and CL version 5.2, update to Command Link version 5.2.86.139 (5.21 Beta, dated 1/10/01) or newer. Go to http://www.competitiondata.com/downloads and follow the link to the updates page or check the readme.txt file installed in your \<i>program files\track master\documents</i> folder. If you are running TM and CL version 5.1 or lower, you must purchase an upgrade to 5.2 			
 ISSUE # CL-3 Command View <i>View Live</i> <i>Readings</i> works the first time you do it, but then fails on subsequent attempts. Applies to: Windows 2000 Professional (may apply to NT 4.0) Commander II ROM versions 33 and lower ONLY Command Link with Command View option 	 First, try the items listed in ISSUE # CL-1 (above) If you still have the problem, you must press the reset button on the Commander II just prior to doing a <i>View Live</i> in Command View. This problem is due to a quirk in Windows 2000 which we are hoping Microsoft fixes in their next release. Check their web site for the availability of a service pack for the version of Win 2000 you have. Commander II ROM 34 and higher eliminates this problem 			

PROBLEM	CAUSE and/or SOLUTION
 ISSUE # CL-4 Command View View Live Readings does not work at all with Commander II ROM 30 and lower Applies to: Windows 2000 Professional (may apply to NT 4.0) Commander II ROM versions 30 and lower Command Link with Command View option 	Contact CDS to arrange for a ROM upgrade to your Commander II
 ISSUE # CL-5 Can not communicate at all with Commander II. Symptoms: Green light on Commander II flashes erratically or freezes when communication cable is connected. This will occur even if CL is not running on the PC <i>Calibration Command</i> buttons in CL become disabled intermittently when communication cable is connected. Applies to: Windows ME, 2000 Professional, XP All Commander II ROM versions. Command Link all versions 	 Cause: The combination of your PC Hardware and Windows version result in an RS 232 (COM) port which does not behave per the RS 232 specification. The COM port is constantly sending "garbage" characters. Possible Solution #1: Version 5.3 of CL has been found to "fix" this problem on some PCs. If you have CL and TM version 5.2 and have this problem you will receive CL 5.3 free of charge. Contact CDS for availability. Possible Solution #2: Re-installation of the Operating system (windows) may be required.

ISSUE # CL-5a	
 Can not download data from Commander II. (wire-transfer models only) Symptoms: The <i>Retries</i> number on the CL download screen counts up, but no records are received. Applies to: Windows ME, 2000 Professional, XP Commander II ROM versions 34 and lower. All Command Link versions.	Contact CDS to arrange a ROM upgrade (to F35 or higher) for your Commander II
	Cause: You have signal names included in your <i>car file</i> which are not in the <i>Default Signal Attributes</i> table.
 ISSUE # CL-6 Command View View Live Readings give error message "out of memory" when trying to view live readings. Applies to: All operating systems All Commander II ROM versions Command Link version 5.3 	 Solution: Start Track Master an verify that you are running version 5.3 by clicking <i>help</i> then <i>About Track Master</i>. The revision number should be 5.3.168.184 or higher Next, click <i>System</i> then <i>Track Master Options</i> then <i>Default Signal Properties</i> Check each signal used in your car file against the list of signals in the <i>Default Signal Properties</i>. Find the signals which AREIN you car file but NOT LISTED in the Default signal properties. Click the Add button and type each one of them in. Close Track Master and Command Link Re-start Command Link. If you continue to get this error you have not included or possibly miss- typed one of the signals. When creating new signal names, always create in TM first
	FIXED IN VERSION 5.3.99.190
ISSUE # CL-7 Command View View Live Readings give error message "cds error" when trying to view live readings. Applies to:	 Cause: The PC you are using to try to <i>view live readings</i> with does not have an exact copy of the car file which was either uploaded to the Commander II (if you have internal memory Commander II) or used to prepare the memory card. Solution: Upload the setup to the Commander II or prepare the memory card
All operating systemsAll Commander II ROM versions	using the same PC as you are using for communication purposes.If your team uses multiple PC's, copy the car file from the main PC to all the other PCs which you wish to use for communication
• All versions of Command Link	

PROBLEM

 ISSUE # TM-3 After copying data from 1 PC to another, you are unable to access (plot) the copied data. Applies to: Track Master version 5.2 	 SOLUTION Upgrade to TM version 5.3 Contact CDS by phone or check our web site, <u>www.competitiondata.com</u>
 ISSUE # CL-8 Command Link will not run. When starting CL, you get a issues warning "failed to load drivers, please re-install software before contacting CDS" Applies to: Command Link 5.3 Windows XP 	 SOLUTION Do not use "compatiability settings on XP. Run software in "native" XP mode. Right click on the shortcut to CL on your desktop Left click on <i>Properties</i> Click the <i>Compatibility</i> Tab Make sure the "<i>Run this program in compatibility mode</i>" is NOT checked.
 ISSUE # TM-3, CL-9 Either program behaves sluggishly or locks up from time to time. Applies to: All versions of CL lower than 5.4 Windows XP & 2000 professional 	 SOLUTION Compatibility problem. Do not run both applications at the same time. Close CL when you want to run TM, and visa versa. Resolved in CL version 5.4
 ISSUE # CL-10 Communication problems when viewing live or wire transfer download. Lots of retries when downloading. Lots of errors when viewing live with Command View Erratic or non-sensible values when viewing live with Command Link Applies to: All versions of CL lower than 5.4 Windows XP & 2000 professional 	 SOLUTION Compatibility problem. Do not run both TM and CL applications at the same time. Close TM when you want to run CL. Resolved in CL version 5.4

PROBLEM CAUSE and/or SOLUTION			
 ISSUE # CL-11 Command Link will not run. When starting CL, you see the "splash" screen, then nothing. Applies to: Command Link 5.3 All versions of Windows 	 Cause: CL 5.3 requires that you have a COM 1 serial port installed on your PC. You do not necessarily need to use COM 1 with CL, but it must be installed on the PC. SOLUTION In the windows device manager, assign your COM port to be COM 1. Note that if you are using a USB to serial converter for COM 1, it must be plugged in to the PC for CL to start OR - Contact CDS for update to CL 5.31 or higher FIXED IN VERSION 5.3.99.190 		
10-28-2002 Release of CL and TM 5.4	All known TM and CL issues with Windows XP are now resolved with release 5.4 Note that Memory card configuration issues (which are operating system issues, not TM or CL issues) still exist		
ISSUE # PC-1 PC does not recognize memory card. Applies to: Windows XP (all versions)	 SOLUTION First, see the item in the Microsoft knowledge base located at : <u>http://support.microsoft.com/search/preview.aspx?scid=kb;en-us;Q310772</u> This article is reprinted in appendix B of this document. The essence of this article is that you must install Windows XP service pack #1 on your machine. This can be done at this link: <u>http://support.microsoft.com/default.aspx?scid=kb;en-us;Q322389</u> If after installing service pack 1 your PC still does not recognize your memory card, follow the instructions in appendix A of this document. 		
 ISSUE # C2-1 When using multiple sample rates in your CAR file configuration (HIGH and MEDIUM rate for example) Only the channels set to HIGH rate get recorded. The Signal List in TM offers the medium speed channels, but when you plot them there is no data in them. Applies to: All Commander II with ROM versions 41 	 CAUSE: This bug is triggered by "viewing live" data, zeroing sensors, or calibrating sensors and then immediately recording data. Some of the program variables were not being properly reset in the Commander II firmware after doing the "View Live" tasks. TEMPORARY WORKAROUND: Whenever you view live readings, zero sensors, or calibrate sensors, after you are done then re-prepare the memory card (or upload the configuration if you have an internal memory Commander II) BEFORE you attempt to record data. PERMANENT SOLUTION: Have your Commander II upgraded to ROM version 43. If you have ROM 41 This will be done at no charge. 		

PROBLEM

CAUSE and/or SOLUTION

ISSUE # USB-1 Command Link issues message "Commander must be connected"	NOTE: CL issues this message even though you do have the Commander II connected and have the correct COM port set in the <i>Communications Setup</i> of CL.		
when attempting to view live, clear, calibrate, etc	Not all PC's running XP or 2000 experience this problem. CAUSE: This is a bug in the edgeport software when running XP.		
 Applies to: Command Link 5.4 & lower Windows XP & 2000 Edgeport USB to Serial adapter 	TEMPORARY WORK AROUND Make a "trip" through the <i>Communications setup</i> tab in CL (click its tab then click back to <i>Commander Communications</i>) before trying to communicate through the edgeport. This activates the edgeport so that it works properly when you actually try to communicate.		
ISSUE # USB-2	NOTE: You only have to make this "trip" once after booting CL. If you close CL you will need to do it again before communicating.		
 Command Link may get stuck in a loop when wire transfer downloading a Commander II through an edgeport USB-COM adapter. "Retries" count up endlessly and download is "stuck" Applies to: Command Link 5.4 & lower Windows XP & 2000 Edgeport USB to Serial adapter Internal memory (wire transfer download) Commander II 	 CAUSE: This is a bug in the edgeport software when running XP. NOTE: Not all PC's running XP or 2000 experience this problem. This problem seems to only occur infrequently so the usual cure is to: Unplug download cable Hit reset button on Commander II Close then re-open CL and try again. If the problem reoccurs frequently then change the settings for the edgeport. Follow the instructions for issue #CL 1 at the beginning of this guide. 		

Memory Card Driver installation for Windows 2000 & XP

If your memory card is not working (no removable drive shown in "my computer" when the card is inserted), then follow these instructions.

VERY IMPORTANT! Verify that you are using a CDS supplied memory card. There are many SRAM memory cards on the market that simply do not work <u>and can not be made to work</u> under Windows 2000 and XP.

NOTE FOR XP USERS ONLY: First verify that you have XP service pack 1 or higher installed on your PC. See issue# PC-1 (Above).

I. Driver installation Procedure

Insert Card in PC

- 1) When you first insert a memory card in the PC the Windows 2000 hardware setup process begins when the "Found New Hardware Wizard" starts. If the wizard does not start, go to the instructions below to **Update Driver for Card**.
- 2) In the first screen of the Wizard, click the button to *Install from a list or specific location*.

Then click Next.



3) Now you should see the *Search Options* dialog box. Click the *Don't search*, *I* will choose driver to install button.

Then click Next.

Search for the best driver in these locations. Use the check boxes below to limit or expand the default search, which includes local paths and removable media. The best driver found will be installed.
Search removable media (floppy, CD-RIOM)
Include this location in the search:
D:\Downloads\Olympus\win 2000 usb driver\Win200
Don't search. I will choose the driver to install. Shoose this option to select the device driver from a list. Windows does not guarantee that the driver you choose will be the best match for your hardware.
< Back Next > Cancel

4) Now you should see the *Hardware* type dialog box. Click on PCMCIA and Flash memory devices.

Generic, then on the right side click

NOTE: if there is a Show Compatible

Generic PCMCIA Memory Card.

Then click Next.

Found New Hardware Wizard Hardware Type. Select a hardware type, and then click Next Common hardware types: NT Apm/Legacy Support 🔋 PCMCIA adapters PCMCIA and Flash Ports (COM & LPT) 🚵 Printers Rrocessors SBP2 IEEE 1394 Devices SCSI and RAID controllers -Smart nard readers < Back Next > Cancel Found New Hardware Wizard 5) Now you should see the *Select Device* Select the device driver you want to install for this hardware. *driver* dialog box. On the left side click Select the manufacturer and model of your hardware device and then click Next. If you E have a disk that contains the driver you want to install, click Have Disk hardware check box in the dialog. Un-Manufacturer ic PCMCIA Memory Card Centennial Technologies, Inc Gener Generi 2 Hitachi Maxell Ltd. M-Systems Flash Disk Pioneers Sieko Epson Have Disk 🙀 This driver is digitally signed. Tell me why driver signing is important

< Back

Next>

Cancel

×

NOTE: You might receive a *Update Driver* warning. If you do, click Yes.

check the option.

Then click Next.

Installing this device driver is not recommended because Windows cannot verify that it is compatible with your hardware. If the driver is not compatible, your hardware will not work correctly and your computer might becor unstable or stop working completely. Do you want to continue installing this driver? Yes No 6) Click *Finish* to complete the should recognize the memory card as a removable drive. (see Verifying That Your PC Recognizes

installation. Click YES when you are asked to re-start windows. After windows re-starts your PC the Cards Properly in chapter 1 of this manual.) If your PC still does not recognize the card, refer to the Update Driver section below.

Update Driver Warning

If you still have problems, verify that you are using a CDS supplied memory card. There are many SRAM memory cards on the market that simply do not work and can not be made to work under Windows 2000 and XP. If you have an old card or one not supplied by CDS, contact CDS to purchase a compatible card.

VERY IMPORTANT NOTE: in windows XP and 2000 you must "Stop" the memory card before removing it from the machine. See the section "Removing Memory Cards When Running Windows 2000 & XP" in chapter 1.

II. Update Driver for Card

if you have already inserted a memory card (before reading these instructions) and another driver has been installed for it you will not see the Wizard when you insert the card in your PC, but you probably will see a message that the card is not working properly.

Update the driver for the card as follows:

Insert Card in PC

- 1) Right-click on the My Computer icon on your desktop. Then left click on Properties.
- 2) Click the *Hardware* tab, then click *Device Manager*. You will see a list of devices installed on your computer.

🚇 Device Manager	- O ×
<u>A</u> ction ⊻iew + → ■ 🖬 😭 🕄 🕄 😹 🔀	
E	
🗄 📃 Computer	
🗄 🖅 🗇 Disk drives	
📄 🚍 Display adapters	
E → DVD/CD-ROM drives	
🖻 🚍 Floppy disk controllers	
E Floppy disk drives	
🕀 🚍 IDE ATA/ATAPI controllers	
🗄 🎲 Keyboards	
🛱 🚭 Memory technology driver	
M-Systems DiskOnChip 2000	
\oplus Mice and other pointing devices k	
🗄 🧶 Modems	
🗄 🖳 🖳 Monitors	
🗄 🥎 PCMCIA adapters	
🗄 🚽 Ports (COM & LPT)	
🗄 🍕 Sound, video and game controllers	
🗄 🖳 System devices	-

- 3) Find the device in the list that is not working, as indicated by the yellow "!" next to it. It will usually be listed under *Memory Technology driver* or under *PCMCIA and Flash memory devices*.
- 4) Left-click on the device then click the *Action* menu at the top and select *Update Driver*.
- Now go to step 2 in the Driver Installation Procedure section (above)

Microsoft Knowledgebase article: PCMCIA Device May Not Work in Windows XP

The information in this article applies to:

- Microsoft Windows XP Home Edition
- Microsoft Windows XP Professional

SYMPTOMS

A Personal Computer Memory Card International Association (PCMCIA) device that works correctly in Microsoft Windows 98, Microsoft Windows 98 Second Edition, Microsoft Windows Millennium Edition, and Microsoft Windows 2000, may not work correctly in Windows XP. If this problem occurs, a black exclamation point (!) on a yellow field is displayed on the device in Device Manager. Additionally, no resources will be allocated to the device.

CAUSE

This problem can occur if the PCMCIA device has its configuration information in common (working) memory instead of attribute memory (where the Card information structure (CIS) and configuration registers are mapped). The Pcmcia.sys driver in Windows XP does not recognize such devices, and because of this, does not allocate resources to the device.

RESOLUTION

To resolve this problem, obtain the latest service pack for Windows XP. For additional information, click the following article number to view the article in the Microsoft Knowledge Base:

Q322389 How to Obtain the Latest Windows XP Service Pack

The English version of this fix should have the following file attributes or later:

Date	Time	Version	Size	File name	Platform
25-Oct-2001	08:07	5.1.2600.17	116,352	Pcmcia.sys	Intel
25-Oct-2001	08:07	5.1.2600.17	310,784	Pcmcia.sys	ia64

STATUS

Microsoft has confirmed that this is a problem in the Microsoft products that are listed at the beginning of this article. This problem was first corrected in Windows XP Service Pack 1.

First Published: Oct 17 2001 9:18AM

Keywords: kbenv kbhw kbtool kbOSWin2000fix kbWinXPpreSP1fix kbWinXPsp1fix kbbug pc card